



The food Air is also at star level in the Restaurant „La Cuisine Rademacher“.

CASE STUDY - AIR PURIFIERS



The User

Enduser: La Cuisine Rademacher
Dellbrücker Hauptstr. 176
51069 Köln
www.la-cuisine-koeln.de

Industry: Hotels & Restaurants

The challenge: The dining room of the restaurant has 40 seats and a room volume of 216 m³. An air exchange rate of 4-8 is recommended to achieve adequate ventilation. For the restaurant, an air exchange rate of 6, i.e. a filtration of the entire room air every 10 minutes, is aimed for.

The starting point

The restaurant “La Cuisine Rademacher”, founded in Cologne in 2018, was recently awarded a star by the Michelin Guide. Due to the pandemic and the associated lockdown, the restaurant can currently only offer a take-away.

Although guests unfortunately cannot be entertained personally in the restaurant, owner Marlon Rademacher has already decided in favor of the AstroPure 2000 air purifier. “On the one hand, we want to supply our employees with HEPA-filtered air in order to significantly minimize the risk of infections, on the other hand, of course, we also want to offer our guests this added value – viruses are everywhere,” says Rademacher.

The solution


Since there is no ventilation system, the mobile AstroPure 2000 now makes it possible to reliably guarantee the necessary exchange of air in the restaurant. The device is able to deliver up to 2000 m³ / h HEPA-filtered air. This achieves an air change rate of more than 6 air changes per hour for the entire room. The noise level is very low, so that the AstroPure 2000 can also be operated without any problems during the restaurant’s operating hours.



“The purchase of the air purifier was a very important step for us to get back to normal. The low volume of the device really surprised us and is therefore in no way disturbing for our guests”.

Marlon Rademacher

Daikin Europe N.V. Naamloze Venootschap · Zandvoordestraat 300 · 8400 Oostende · Belgium · www.daikin.eu · BE 0412 120 336 · BE 0412 120 336 (Responsible Editor)



ECPEN21-706

06/2021

The present publication is drawn up by way of information only and does not constitute an offer binding upon Daikin South Africa. Daikin South Africa has compiled the content of this publication to the best of its knowledge. No express or implied warranty is given for the completeness, accuracy, reliability or fitness for particular purpose of its content and the products and services presented therein. Specifications are subject to change without prior notice. Daikin South Africa explicitly rejects any liability for any direct or indirect damage, in the broadest sense, arising from or related to the use and/or interpretation of this publication. All content is copyrighted by Daikin South Africa.

